



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

P. O. Box 7
Monticello, Utah 84535-0007
(435) 587-1500

File: UTU-68061
Office: (UT-090)

Date: 03/10/11
To: Minerals File UTU-68061
From: Ted McDougall, Geologist
Subject: Surface Management Site Inspection, Denison Mines, Rim/Columbus Mine, UTU-68061 (M037/006), West Summit, San Juan County, Utah.

Date of Inspection: 03/09/11
Time of Inspection: 11:00 A.M.
Participants: Ted McDougall
Legal Description: T. 31 S., R. 25 E., Section 29 and 30
Mining Claims Involved: Humbug, Poor Boy, and Columbus Groups
Claimant/Operator: Denison Mines Corp.

The purpose of the inspection was to monitor activity at the Rim/Columbus Mine. The mine is still idle. Dewatering operations continue to pump and treat mine water.

The operator has opened up a large channel in the waste rock pile in an effort to identify the source of a small seep at the base of the dump. The channel extends from the area of the seep to a point approximately 100-150 feet to the east. A small sump has been excavated at the bottom of the channel at its east end. The sump is currently full of water but it is difficult to determine if water is result of snowmelt or subsurface flow. The operator will likely have to wait until summer before an evaluation can be done.

The gate at the portal is secure and the work areas around the Rim Shaft and Humbug Portal/Shop area have been cleaned up.


RECEIVED E-Mail

APR 11 2011

Div. of Oil, Gas & Mining



Humbug Portal/Shop Area



RECEIVED E-Mail

APR 11 2011

Div. of Oil, Gas & Mining



Channel excavated through waste rock pile with small sump at east end.

RECEIVED E-Mail

APR 11 2011

Div. of Oil, Gas & Mining



Rim Shaft – looking east from area of waste rock pile.

RECEIVED E-Mail

APR 11 2011

Div. of Oil, Gas & Mining